



# Comprehensive

**Car Inspection Report** 



Thorough inspection with

300+ quality checks




Precise insights from

experienced technicians



Trusted by

over 600,000 customers





### **Hyundai Verna**

SX1.5VTVT IVT | 2020 | AT | Petrol

Inspection location: Gurgaon

Report generated on: 24 Apr, 2024



10M +

Inspected

200 + Cars

Cities present

Cars sold

1M+



# **Content of report**

Your report at a glace

Overview of your overall car condition



Inspection summary

Category wise ratings and condition



Detailed Evaluation of each category

- 1. Exterior & Tyres
- 2. Engine & Transmission
- 3. Steering, Suspension & Brakes
- 4. Air Conditioning
- 5. Electricals & Interiors
- 6. Other Details




OEM installed features & specs

1. Safety

- 2. Fuel & Performance
- 3. Entertainment & Communication
- 4. Dimensions & Capacity
- 5. Engine, Transmission & Brakes
- 6. Comfort & Convenience













### 

At CARS24, we inspect cars thoroughly across 140 parameters, ensuring the highest quality. Your car has been inspected and is non-accidental, non-flooded, and non-tampered.

- The car's engine and transmission are in good working condition.
- The exterior has minor scratches and dents, but no major damage.
- The interior is in good condition with minor wear and tear.

Overall, your car is in good condition with minor cosmetic issues.

6,666 kms

### **2** Ownership and fitness

Estimated kms/year:

Ownership number: 1 Registration date: 30 June, 2014

Ownership number: 1 Registration place: Noida, Uttar Pradesh

Ownership type: Individual Fitness validity: 6 Jul, 2036

PUCC validity: 31 March, 2024



### **∠** Transferability details

Blacklisted: No

RTO NOC Issued: 30 June, 2014

Party Peshi Applicability: No

Hypothecation & Yes & Financier Name: HDFC Bank Pvt. Ltd.

#### Vehicle modification

Converted (Commercial ownership to private): **No** 

Migration (Re-registered in another state): **No** 

Adapted for Special Use (Example differently abled): **No** 

### **Legal history details**

Criminal cases: 1 🔔

Road accidents: None reported

Compensation cases: None reported

Civil cases: 1 🛕

Theft cases: None reported

Other cases: None reported

Criminal case

Accident date: 16 June, 2023

Filing date: 15 June, 2023

Place: New Delhi, Delhi

**Violation:** Minor Traffic Violation

Legal position: Accused FIR number: FIR123/2023

FIR summary: Signal jumping incident

Acts/Sections: IPC, Section 279

▲ Civil case: Disposed

Filing date: 1 July, 2023

Disposed date: 1 December, 2023

Place: New Delhi, Delhi

Violation: Contract dispute Legal position: Respondent CNR number: CNR123/2023

Disposal summary: Settled by mutual


agreement

Order judgement summary: Case disposed

with mutual settlement



### **Challan history**



Pay now >



#### 1 Total challans: 2

Date	Offence	Challan no.	Amount	Status
12 Jan, 2025	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT)+2 more	1234567890	₹2,000	Pending
12 Jan, 2025	Improper parking	1234567890	₹1,000	Pending

### (2023)

#### 1 Total challans: 1

Date	Offence	Challan no.	Amount	Status
12 Jan, 2023	Improper parking	1234567890	₹500	Paid

2014

#### i Total challans: 4

A Pending: 2

Date	Offence	Challan no.	Amount	Status
12 Jan, 2014	OVER SPEED (Light Motor Vehicle) (112/183 MV ACT) +2 more	1234567890	₹2,000	Moved to physical court
12 Jan, 2014	Improper parking	1234567890	₹500	Paid
12 Jan, 2014	Improper parking	1234567890	₹500	Moved to physical court
12 Jan, 2014	Improper parking	1234567890	₹500	Paid



# **☆ Inspection summary**

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview.

#### **Exterior & Tyres**

The exterior of the car has scratches and some parts have been repainted. The tyres have a tread depth of 3-5mm.

3.7/5

**Neutral** 

#### 🛱 Engine & Transmission

The engine is in good condition. There are no issues with blow-by, engine sound, or exhaust smoke. However, the engine oil is dirty.

4.5/5

**Excellent** 

### Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that need immediate attention.

4.5/5

**Excellent** 

#### **Air Conditioning**

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

4.7/5

**Excellent** 

#### **Electricals & Interiors**

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera. The interior is in good condition with leather seats and a sunroof.

4.4/5

**Excellent** 



## Vehicle images



















### **01. Exterior & Tyres**

Perfect parts: 26 | Imperfect parts: 25 | Estimated repair cost: ₹10,000



Parameters	Perfect	Imperfect
Boot Floor	<b>Ø</b>	
Pillar LHS A	•	
Pillar LHS B	•	
Pillar LHS C		
Pillar RHS A	0	
Pillar RHS B	0	
Pillar RHS C		
Apron LHS		
Apron RHS		
Apron RHS LEG		
Apron LHS LEG		
Firewall		
Cowl Top		
Upper Cross Member (Bonnet Patti)	<b>②</b>	
Front Show	<b>②</b>	
Lower Cross Member	•	
Radiator Support		





Parameters	Perfect	Imperfect
Head Light Support		
Windshield Rear		
Light LHS Taillight	•	
Light LHS Fog Light	•	
Light RHS Fog Light	•	
ORVM - Manual / Electrical LHS	0	
Tyre Spare Tyre		
Grill	0	
Is the Car Waterlogged?	•	
Roof		•
Bonnet/Hood		•
Dicky Door / Boot Door		•
Quarter Panel LHS		•
Quarter Panel RHS		•
Fender LHS		•
Fender RHS		•
Running Border LHS		•
Running Border RHS		•
Door LHS Front		•





Parameters	Perfect	Imperfect
Door LHS Rear		•
Door RHS Front		•
Door RHS Rear		•
Windshield Front		•
Light LHS Headlight		0
Light RHS Headlight		0
Light RHS Taillight		•
Bumper Front		•
Bumper Rear		•
ORVM - Manual / Electrical RHS		•
Alloy Wheel		•
LHS Front Tyre		•
LHS Rear Tyre		•
RHS Front Tyre		•
LHS Rear Tyre		•



**Engine & Transmission** 

**Electricals & Interiors** 

Steering, Suspension & Brakes

**Air Condition** 

Other Details



Roof: No Dents, Scratched



Bonnet/Hood: No Dents, Scratched



Dicky Door / Boot Door: No Dents, Scratched



Quarter Panel LHS: No Dents, Repainted



Quarter Panel RHS: No Dents, Repainted



Fender LHS: No Dents, Scratched, Repainted



Fender RHS: No Dents, Repainted



Running Border LHS: No Dents, Scratched, Repainted



**Engine & Transmission** 

**Electricals & Interiors** 

Steering, Suspension & Brakes

**Air Condition** 

Other Details



Running Border RHS: No Dents, Repainted



Door LHS Front: No Dents, Scratched, Repainted



Door LHS Rear: No Dents, Repainted, Scratched



Door RHS Front: No Dents, Repainted



Door RHS Rear: No Dents, Repainted



Windshield Front: Scratched



**Engine & Transmission** 

**Electricals & Interiors** 

Steering, Suspension & Brakes

**Air Condition** 

Other Details



Light LHS Headlight: Scratched



Light RHS Headlight: Scratched



Light RHS Taillight: Scratched



Bumper Front: Scratched, Dented



Bumper Rear: Repainted



ORVM - Manual / Electrical RHS: Damaged



Alloy Wheel: Scratched



LHS Front Tyre:



70% life remaining



**Engine & Transmission** 

**Electricals & Interiors** 

Steering, Suspension & Brakes

**Air Condition** 

Other Details





LHS Rear Tyre: 0 30% life remaining



RHS Front Tyre:



70% life remaining





LHS Rear Tyre: 0 30% life remaining



### 02. Engine & Transmission

Perfect parts: 11 | Imperfect parts: 01 | Estimated repair cost: ₹500



Parameters	Perfect	Imperfect
Engine		
Engine Sound		
Exhaust Smoke		
Engine Permissible Blow by (Back Compression)		
Clutch	<b>Ø</b>	



 Exterior & Tyres
 Engine & Transmission
 Electricals & Interiors
 Steering, Suspension & Brakes
 Air Condition
 Other Details

 Parameters
 Perfect
 Imperfect

 Gear Shifting
 ✓
 Imperfect

 Engine Oil Level Dipstik
 ✓
 Imperfect

 Battery
 ✓
 Imperfect

 Coolant
 ✓
 Imperfect

 Sump
 ✓
 Imperfect

 Engine Oil
 Imperfect
 Imperfect

#### 03. Electricals & Interiors

Perfect parts: 14 | Imperfect parts: 00 |



Parameters	Perfect	Imperfect
4 Power Windows		
Airbag Feature		
Music System		
Leather Seat		
Sunroof		
Steering Mounted Audio Control		
ABS		
Rear Defogger		



Parameters	Perfect Imperfect
Reverse Camera	
Electrical	
Interior	
Parking Sensor	
No. Of Airbags	
No. Of Power Windows	

Parameters	Number
No. Of Airbags	2
No. Of Power Windows	4

### 04. Steering, suspension & Brakes

Perfect parts: 02 | Imperfect parts: 01 | Estimated repair cost: ₹4,000



Steering		
oteering		
Suspension		•
Brake	<b>Ø</b>	







### 05. Air Conditioning

Perfect parts: 03 | Imperfect parts: 0



Parameters	Perfect	Imperfect
AC Cooling		
Heater		
Climate Control AC		

#### 06. Other Details

Available: 03 | Not Available: 01



Parameters	Available	Not available
Chassis Embossing		
RC Availability		
Insurance Image		
Duplicate Key		•







**Engine & Transmission** 

**Electricals & Interiors** 

Steering, Suspension & Brakes

**Air Condition** 

Other Details

#### **Total estimated repair cost**

A rough estimate of the cost required to fix identified imperfections in the car, helping you anticipate potential repair expenses before buying/selling.

#### **Total estimated repair cost: ₹14,450**

**Total imperfect parts:27** 



Parameters	Total imperfect parts	Est. Repair Cost
Exterior & Tyres	25	₹10,000
Engine & Transmission	1	₹500
Steering, Suspension & Brakes	1	₹4,000



# **\$** OEM installed features & specs

Understanding the features and specifications of the **Hyundai Verna** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.







### **⊘** Safety

Parameters	Metric
Front Fog Lights	Yes
ISOFIX-Child Seat Anchor Points	Yes
Anti-lock Braking System (ABS)	No
Central Locking	Keyless Entry
Rear Defogger	Yes
Airbags	04

#### **♦ Tuel & Performance**


Parameters	Metric
Max power (bhp)	81.80
Max torque (Nm)	114.7
Fuel tank capacity (lit)	24
Emission Standard	BSIV




#### **a** Entertainment & Communication

Instrument panel type 360 degree camera Speaker brand

Analogue & digital Yes JBL




### ❖ Interior & Exterior





### ∠ <sup>¬</sup> Dimensions & Capacity



## **Engine, Transmission & Brakes**

Parameteres	Metric
Gear Box- No. of Gears	04
Displacement (cc)	1800
Transmission type	Manual
Cylinders	02
Break type (rear)	Drum
Break type (front)	Drum
Number of disc brakes	02



### **Comfort & Convenience**

Parameteres		Metric		
Seat upholstery (cc)		1800		
Auto climate control		Yes		
Wireless charging pad		Yes		
Steering wheel material		Alloy & Syntheti	ic Leather	
Smart Card/Smart Key		Yes		
Top model		Yes		
Parking sensors	Rear AC		Power windows	
No ((合))	Yes		Front & rear	
Steering adjustment		Driver seat adjustment		
Tilt & telescope		Manual		
Cruise control	Air conditoner <b>Yes</b>		Push button start  Yes	<b>E</b>





# Thank you for choosing us!

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition. Thank you once again for your trust and patronage.

#### Other services by

CHALLAN ↗

SERVICE HISTORY **↗** 

PERSONAL LOAN 7





Buying, selling, and financing pre-owned cars is now easier than ever!

Experience CARS24 App on mobile





**Keep in touch** 









