

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 HYUNDAI PALISADE

SMART | 107,089 KM

VIN: KMHR381C6NU347740

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	107089	Specs	Yes
Engine	3.5L	Option Type	Basic
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	7 Seats	Number of keys	2 Keys
VIN number	KMHR381C6NU347740		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Performance			
Paddle Shift	✓	Hill Descent Control	✓

Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door	✓	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board Condition: Low Visual Dent < 50mm, Light Scuffing < 80mm	!

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Monogram	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key
Button Faded

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Rear Left AC Vent

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Minor Scuffing/ Crack/ Fair Use Wear

Central Console

Cup Holder

Steering Wheel

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Headliner

Rear View Mirror

Toolkit

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE