

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 MG RX8

BLACK EDITION | 79,121 KM

VIN: LSJW84W92NG012423

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

Kilometers	79121	Specs	Yes
Engine	2.0L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Four Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	8 Airbags
Seating Capacity	7 Seats	Number of keys	1 Keys
VIN number	LSJW84W92NG012423		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	Side Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Ventilated Seat	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Light Scuffing < 50mm

Rear left door

Rear right door
Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender
Condition: Light Scuffing

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Rear Bumper Condition

Rear Bumper
Rear Bumper: Scuffing > 80mm, Dent < 50mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield
Condition: Driver Side/Stone Chip Mark<5mm

Rear Windshield

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓		

Steering, Suspension & Brakes

Steering

Steering wheel	✓		

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key
Button Faded

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight
Left: Light Scuff Marks < 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights
Right DRL: Low Brightness

Fog Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Rear Left AC Vent

Power/ Manual Windows

Seat Heaters

Memory Seats

Interiors & Luggage

Dashboard And Instrument Panel

Central Console
Gear Shift Knob: Knob Fair Use Wear

Cup Holder

Steering Wheel
Color Faded

Sunvisor Left: Sunvisor LHS Vanity Mirror Light Not Working, Sunvisor RHS Vanity Mirror Light Not Working	!	Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE