

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 SUZUKI DZIRE

GLX | 92,236 KM

Car highlights

Fuel Efficient

Fuel efficient with 22.0 km/L

Great Parking Assistance

Parking Sensors Rear

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	92236	Specs	Yes
Engine	1.2L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	22.0 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MBHZF6C16PG427532		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Exteriors			
Fog Light Front	✓		
Safety & Security			

Parking Sensors Rear ✓	Airbag Driver Front ✓
Airbag Passenger Front ✓	ABS ✓
Entertainment	
Bluetooth Player ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition ✓

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition ✓ | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

Steering, Suspension & Brakes

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key

Button Faded ⓘ

Dashboard

Instrument Panel ✓

Controls ✓ | Cruise Control ✓

Infotainment Display ✓ | Music System ✓

Lights

Headlight ✓ | Interior Lights ✓

Tail Light Cluster ✓ | Fog Lights ✓

Air Conditioning

AC Cooling ✓ | AC System Leaks ✓

Rear Blower Switch ✓

Parking Sensors ✓ | Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel ✓

Central Console
Gear Shift Knob: Knob Fair Use Wear

Cup Holder ✓

Steering Wheel
Color Faded

Sunvisor ✓ | Seat Upholstery ✓

Manual Seat Movement ✓ | Seat Belts ✓

Head Rest ✓ | Door Controls And Trim ✓

Carpet ✓ | Headliner ✓

Rear View Mirror ✓ | Toolkit ✓

Tyres

Tyres Condition

Left Hand Side Front Tyre ✓ | Left Hand Side Rear Tyre ✓

Right Hand Side Front Tyre ✓ | Right Hand Side Rear Tyre ✓

Spare Tyre	✓

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE