

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 NISSAN SUNNY

SV | 57,571 KM

VIN: MDHBN7AD9RG512378

Car highlights

Fuel Efficient

Fuel efficient with 18.0 km/L

Bluetooth

Enjoy your drive with bluetooth

Music System

Enjoy your drive with music system

Amazing Comfort

Power driver seat

Basic Details

Kilometers	57571	Specs	Yes
Engine	1.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	18.0 km/L mileage
Wheel Type	Steel Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MDHBN7AD9RG512378		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Entertainment			
Bluetooth Player	✓		
Safety & Security			

Airbag Driver Front ✓	Airbag Passenger Front ✓
ABS ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition

Light Scuffing < 50mm ⓘ | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

Steering, Suspension & Brakes

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE