

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 NISSAN PATHFINDER

SL | 50,394 KM

VIN: 5N1DR3MR8RC257710

Car highlights

Panoramic Roof

This car has a panoramic roof

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

Kilometers	50394	Specs	Yes
Engine	3.5L	Option Type	Fully Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel Efficiency	9.1 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	11 Airbags
Seating Capacity	8 Seats	Number of keys	2 Keys
VIN number	5N1DR3MR8RC257710		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Heads up Display	✓	Climate Control AC	✓
Cruise Control	✓	Memory Seats	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Ventilated Seat	✓	Power Tailgate/ Power Trunk	✓
Power Windows Rear	✓		

Safety & Security			
Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Front Camera	✓
Side Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Knees	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Paint Chip-off < 5mm

Rear left door

Rear right door

Fenders Condition

Left Fender
Condition: Paint Chip-off

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield

Rear Windshield

Structural Assessment

Chassis Condition

Apron

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key	✓

Dashboard

Instrument Panel	✓
Controls	✓
Cruise Control	✓
Infotainment Display	✓
Music System	✓
Camera	✓

Lights

Headlight	✓
Interior Lights	✓
Tail Light Cluster	✓
Daylight Running Lights	✓
Fog Lights	✓

Air Conditioning

AC Cooling	✓
AC System Leaks	✓
Rear Blower Switch	✓
Rear Left AC Vent	✓
Power/ Manual Windows	✓
Seat Heaters	✓
Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓
Central Console	✓
Cup Holder	✓
Steering Wheel	✓
Sunvisor	✓
Seat Upholstery	✓
Manual Seat Movement	✓
Seat Belts	✓
Head Rest	✓
Door Controls And Trim	✓
Carpet	✓
Headliner	✓
Rear View Mirror	✓
Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE