

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 JAC J7

INTELLIGENT | 80,253 KM

VIN: LJ12FKT37P4014954

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	80253	Specs	Yes
Engine	1.5L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Red
Interior Trim	Leather Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LJ12FKT37P4014954		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓

Airbag Sides	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Exteriors			
Running Lights	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing, Paint Chip-off	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Low Visual Dent, Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Chip< 8mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip	!	Rear Windshield	✓

Mark<5mm, Air Bubbles

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top
Fair Use Wear/Crack<5mm ⓘ

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight
Left: Scuff Marks > 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted

Central Console
Gear Shift Knob: Knob Fair Use Wear

Cup Holder

Steering Wheel

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE