

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 MG GT

LUXURY | 79,436 KM

VIN: LSJA36U99RN017157

Car highlights

Sunroof

This car has a sunroof

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	79436	Specs	Yes
Engine	1.5L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	LSJA36U99RN017157		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Lane Departure Warning System	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Collision Warning System	✓	Front Camera	✓
Side Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Performance			
Paddle Shift	✓		
Exteriors			
Running Lights	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓		

Hood Condition

Hood Bonnet: Acid Marks/ Bird Dropping < 5mm	!		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓		

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Manual Key Not Available

Dashboard

Instrument Panel ✓

Controls ✓ | Cruise Control ✓

Infotainment Display ✓ | Music System ✓

Camera ✓

Lights

Headlight ✓ | Interior Lights ✓

Tail Light Cluster ✓ | Daylight Running Lights ✓

Air Conditioning

AC Cooling ✓ | AC System Leaks ✓

Rear Blower Switch ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel ✓

Central Console
Gear Shift Knob: Knob Fair Use Wear !

Steering Wheel
Color Faded !

Sunvisor ✓

Seat Upholstery ✓ | Manual Seat Movement ✓

Seat Belts ✓ | Head Rest ✓

Door Controls And Trim ✓

Carpet
Front Left Floor Mat: Smudge/Burn/Crack !

Headliner ✓ | Rear View Mirror ✓

Toolkit ✓

Tyres

Tyres Condition

Left Hand Side Front Tyre ✓ | Left Hand Side Rear Tyre ✓

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<45%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE