

RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2023 MITSUBISHI ATTRAGE

GLX HIGHLINE | 122,775 KM

VIN: MMDAFT6J3PH000589

Car highlights

Fuel Efficient

Fuel efficient with 20.2 km/L

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	122775	Specs	Yes
Engine	1.2L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	20.2 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MMDAFT6J3PH000589		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓	Rear Bumper Spoiler	✓
Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Entertainment			

Bluetooth Player	✓		
Safety & Security			
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top
Fair Use Wear/Crack<5mm

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Grill Condition Light Scuffing < 50mm	!	Monogram	✓

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key
Button Faded

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System
Steering Mounted Audio Controls: Button(s) Faded ⓘ

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Fog Lights ✓

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted ⓘ

Central Console
Gear Shift Knob: Knob Fair Use Wear ⓘ

Cup Holder ✓

Steering Wheel
Steering Wheel Fair Use Wear ⓘ

Sunvisor ✓

Seat Upholstery
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks ⓘ

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet
Front Left Floor Mat: Smudge/Burn/Crack ⓘ

Headliner ✓

Rear View Mirror ✓

Toolkit ✓

Tyres

Tyres Condition

Left Hand Side Front Tyre ✓

Left Hand Side Rear Tyre ✓

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE