

RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2022 NISSAN KICKS

SL | 122,481 KM

VIN: 3N1CP5CP7NL503150

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera, Parking Sensors Rear & more

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	122481	Specs	Yes
Engine	1.6L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	16.7 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Blue
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	3N1CP5CP7NL503150		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Safety & Security			
Lane Departure Warning System	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Fully Repainted	!		

Hood Condition

Hood	✓		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Edge Scuffing

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Fully Repainted

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Steering Mounted Audio Controls: Not Working Properly

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Fog Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Left AC Vent

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Steering Wheel

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Headliner

Rear View Mirror

Toolkit

Tyres

Tyres Condition

Left Hand Side Front Tyre

Left Hand Side Rear Tyre

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE