

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 INFINITI QX30

STD | 97,565 KM

VIN: SJKCH5CR3JA000192

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	97565	Specs	Yes
Engine	2.0L	Option Type	Basic
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	9 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	SJKCH5CR3JA000192		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	Side Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Exteriors			
Fog Light Front	✓	Running Lights	✓
Performance			
Paddle Shift	✓		
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We���re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Paint Defect

Rear right door
Panel: Light Scuffing < 50mm

Rear left door
Panel: Door inner beading damaged

Fenders Condition

Left Fender
Condition: Low Visual Dent, Light Scuffing, Wheel arch rusted/ cracked / dirty

Right Fender
Right Fender: Wheel arch cracked

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm, Crack/ Misaligned

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition

Apron

Boot Floor ✓

Firewall Condition ✓

Head Light Support Condition ✓

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓

Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim
Rim: Alloy Edge Scuffing !

Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim
Rim: Alloy Edge Scuffing !

Right Rear Alloy/ Rim
Rim: Alloy Edge/Scuffing !

Grill Condition
Scuffing > 50mm !

Monogram ✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body ✓

Engine Performance ✓

Engine Oil (Condition & Level) ✓

Exhaust System ✓

Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓

Drive Axle ✓

Steering, Suspension & Brakes

Brake System

Parking Brake ✓

Brake Master Cylinder ✓

Brake Fluid
Front Brake Discs Thickness < Manufacturer Standard !

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key

Remote/Boot Not Opening

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Left: Scuff Marks > 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights

Right DRL: Low Brightness

Fog Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Crack

Power/ Manual Windows

Seat Heaters

Memory Seats

Driver Seat: Minor Switch Color Faded/ Peel-off

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted

Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing

Steering Wheel

Color Faded

Sunvisor

Seat Upholstery

Rear Left Seat: Minor Smudge/ Crack

Manual Seat Movement

Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet Front Left Floor Mat: Smudge/Burn/Crack	!
Headliner Front Left: Light Smudge/Disfiguration	!	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE