

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 BMW X1

XDRIVE 25I | 96,477 KM

VIN: WBAJG9105JEA99776

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	96477	Specs	Yes
Engine	2.0L	Option Type	Fully Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	10 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	WBAJG9105JEA99776		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Heads up Display	✓	Climate Control AC	✓
Cruise Control	✓	Memory Seats	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			

Fog Light Front	✓	Running Lights	✓
Safety & Security			
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Dent > 50mm, Light Scuffing < 80mm	!		

Hood Condition

Hood Bonnet: Paint Chip-off < 5mm	!		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass Noise/Vibration	!		

Windshield Condition

Front Windshield Condition: Front Wiper blades need	!	Rear Windshield Wiper washer not working	!

replacement

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top Fair Use Wear/Crack>5mm	!

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror Body: Light Scuffing	!

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing	!
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Performance	✓	Engine Oil (Condition & Level)	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System ✓

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster
Left Tail Lamp: Crack / Fair Use Wear > 5mm !

Daylight Running Lights
Right DRL: Low Brightness !

Fog Lights ✓

Air Conditioning

AC Cooling
AC Temperature: AC Hot Air Not Working !

AC System Leaks ✓

Rear Blower Switch ✓

Power/ Manual Windows ✓

Memory Seats ✓

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted !

Central Console
Box: Crack/Fair Use Wear/ Scuffing !

Cup Holder ✓

Steering Wheel
Steering Wheel Fair Use Wear !

Sunvisor ✓

Seat Upholstery
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off !

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim !

		Front Left Door: Crack/Fair Use Wear	
Carpet Front Left Floor Mat: Floor Mat Missing	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE