

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 PEUGEOT 3008

GT LINE | 81,763 KM

VIN: VF3M45GY4PS005222

Car highlights

Panoramic Roof

This car has a panoramic roof

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	81763	Specs	Yes
Engine	1.6L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	15.7 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Blue
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	VF3M45GY4PS005222		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Front Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door	✓	Rear left door	✓
Rear right door Panel: Scuffing > 50mm	!		

Fenders Condition

Left Fender Condition: Wheel arch rusted/ cracked / dirty	!	Right Fender Right Fender: Dent	!

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement	!	Rear Windshield Wiper not working	!

Structural Assessment

Chassis Condition	✓	Apron	✓

Boot Floor ✓

Firewall Condition ✓

Head Light Support Condition ✓

Cowl Top

Cowl Top
Not Fixed Properly !

Rear View Mirror Condition

Left Hand Side Mirror ✓

Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim
Rim: Alloy Face Scuffing !

Right Front Alloy/ Rim ✓

Right Rear Alloy/ Rim ✓

Monogram ✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Performance ✓

Engine Oil (Condition & Level)
Engine oil sludge !

Exhaust System ✓

Turbocharger/ Supercharger ✓

Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓

Drive Axle ✓

Steering, Suspension & Brakes

Brake System

Parking Brake ✓

Brake Master Cylinder ✓

Brake Fluid
Front Brake Discs Thickness < Manufacturer Standard !

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure ⓘ

Warning Light

Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE