

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 MITSUBISHI MONTERO SPORT

SIGNATURE | 89,712 KM

VIN: MMEMC71X5KH009467

Car highlights

Four wheel drive

This car has a Four wheel drive

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	89712	Specs	Yes
Engine	3.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Four Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	2 Airbags
Seating Capacity	7 Seats	Number of keys	2 Keys
VIN number	MMEMC71X5KH009467		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		

Exteriors			
Fog Light Front	✓	Running Lights	✓

Rear Bumper Spoiler	✓		
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Differential Locks	✓		
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Rear Seat Entertainment	✓	Bluetooth Player	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Scuffing > 50mm

Rear left door

Rear right door
Panel: Scuffing > 50mm

Fenders Condition

Left Fender
Condition: Low Visual Dent

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Rear Bumper Condition

Rear Bumper
Rear Bumper: Paint Faded

Hood Condition

Hood
Bonnet: Paint Damage/ Low Brightness

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board
Condition: Chrome/ Rubber/ Plastic Fair Use Wear

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror Body: Paint Faded	!	Right Side Mirror Body: Paint Defects	!

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓		

Transmission Operation

Drive Axle	✓	4*4 Condition (If Applicable)	✓

Steering, Suspension & Brakes

Steering

Steering wheel	✓		

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key

Remote/Functions Not Responding

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Steering Mounted Audio Controls: Button(s) Faded

Camera

Lights

Headlight

Left: Low Brightness lamps, Cracks/ Holes

Interior Lights

Tail Light Cluster

Daylight Running Lights

Fog Lights

Left Fog Light: Cracks/ Holes/ Fair Wear Use

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Rear Left AC Vent

Rear Entertainment

Power/ Manual Windows

Front Left: Power Window Noise/Vibration

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Scuffing/ Disfiguration/ Melted, Minor Color Dullness, Minor Scuffing/ Crack/ Fair Use Wear

Central Console

Cup Holder

Rear Central: Broken/Fair Use Wear

Steering Wheel

Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery

Driver Seat: Smudge/ Cracks, Leather/Fabric Fair Use Wear/Tears

Manual Seat Movement

Seat Belts

Head Rest	✓	Door Controls And Trim	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror Mirror Assembly Loose	!	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE