


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2024 EXEED LX**

**COMFORT | 73,384 KM**

VIN: LVTDB21B3RE900168

## Car highlights

### Boosted Engine

This car has a Boosted Engine

### Cruise control

Cruise control to drive with ease & comfort

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 73384 | Specs | Yes |
| Engine | 1.5L | Option Type | Basic |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Red |
| Interior Trim | Leather Trim | Number of Airbags | 4 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | LVTDB21B3RE900168 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Power Tailgate/ Power Trunk | ✓ | Power Windows Rear | ✓ |
| **Safety & Security** | | | |
| Lane Departure Warning | ✓ | Navigation | ✓ |

| | | | |
|---|---|---|---|
| System | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Sides | ✓ | Airbag Driver Front | ✓ |
| Airbag Passenger Front | ✓ | ABS | ✓ |
| **Performance** | | | |
| Paddle Shift | ✓ | Hill Descent Control | ✓ |
| **Exteriors** | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | | |

# 150 Point Detailed Inspection Report

We���re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Low Visual Dent < 30mm | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

### Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition ⓘ
Scuffing > 50mm

Monogram ✓

Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Turbocharger/ Supercharger ✓ | Radiator Condition ✓

Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

## Steering, Suspension & Brakes

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

Keys

Master Key
Button Faded ⓘ

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Music System | ✓ |
| Camera | ✓ | | |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights<br>Right DRL: Low Brightness, Lamps Are Not Working | ! |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Blower Switch | ✓ | Rear Left AC Vent | ✓ |
| Power/ Manual Windows | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |

| | | | |
|---|---|---|---|
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <45% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <45% | RHS Rear Tyre | <75% |
| Spare Tyre | <45% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE