

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 ALFA ROMEO GIULIA

VELOCE | 25,167 KM

VIN: ZAREAEDN0N7668925

Car highlights

Panoramic Roof

This car has a panoramic roof

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	25167	Specs	Yes
Engine	2.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Rear Wheel Drive
Body Type	SEDAN	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	8 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	ZAREAEDN0N7668925		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	Lane Departure Warning System	✓
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Auto Park Assist	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Airbag Sides	✓

Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Performance			
Paddle Shift	✓		
Exteriors			
Running Lights	✓		
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Light Scuffing < 50mm

Rear left door

Rear right door
Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Light Scuffing

Rear Bumper Condition

Rear Bumper
Rear Bumper: Scuffing > 80mm, Colour Mismatch/ Low Brightness

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement, Driver Side/Stone Chip Mark<5mm

Rear Windshield

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top Fair Use Wear/Crack>5mm	!

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel Water Channel Rusty	!

Engine & Transmission

Engine

Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓	Turbocharger/ Supercharger	✓
Radiator Coolant	✓		

Transmission Operation

Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key
Button Faded

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Power/ Manual Windows

Seat Heaters

Memory Seats

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear

Central Console

Cup Holder

Steering Wheel
Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE