


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2024 NISSAN SUNNY**

**SV | 64,915 KM**

VIN: MDHBN7AD1RG519597

## Car highlights

### Great condition

Car has low imperfections

### Great Parking Assistance

Parking Sensors Rear

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 64915 | Specs | Yes |
| Engine | 1.5L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel Efficiency | 18.0 km/L mileage |
| Wheel Type | Steel Wheels | Exterior Color | Exterior Color Silver |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | MDHBN7AD1RG519597 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Airbag Driver Front | ✓ |
| Airbag Passenger Front | ✓ | ABS | ✓ |
| **Comfort & Convenience** | | | |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| **Entertainment** | | | |

| | |
|---|---|
| Bluetooth Player | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Low Visibility Dent < 30mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | | | |
|---|---|---|---|
| Rear Bumper<br>Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Paint Faded | ! | | |

### Hood Condition

| | | | |
|---|---|---|---|
| Hood | ✓ | | |

### Roof Condition

| | | | |
|---|---|---|---|
| Roof | ✓ | | |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition ✓ | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

## Steering, Suspension & Brakes

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Parking Sensors | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |

| | | | |
|---|---|---|---|
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE