


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2022 TOYOTA PRADO**

**GXR | 57,560 KM**

VIN: JTEBU3FJ7N5095631

## Car highlights

### Service History

Service history available

### Cruise control

Cruise control to drive with ease & comfort

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 57560 | Specs | Yes |
| Engine | 4.0L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Four Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Blue |
| Interior Trim | Fabric Trim | Number of Airbags | 9 Airbags |
| Seating Capacity | 7 Seats | Number of keys | 2 Keys |
| VIN number | JTEBU3FJ7N5095631 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Cool Box | ✓ | Power Windows Rear | ✓ |
| **Exteriors** | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |

| | | | |
|---|---|---|---|
| Rear Bumper Spoiler | ✓ | | |
| **Safety & Security** | | | |
| Navigation | ✓ | Parking Sensors Front | ✓ |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Sides | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Knees | ✓ | Airbag Driver Front | ✓ |
| Airbag Passenger Front | ✓ | ABS | ✓ |
| **Performance** | | | |
| Differential Locks | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | | |

# 150 Point Detailed Inspection Report

We���re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Light Scuffing < 50mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Light Scuffing < 50mm | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Monogram

Panel Condition

Rear Trunk Panel

## Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

4*4 Condition (If Applicable)

## Steering, Suspension & Brakes

Steering

Steering wheel

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

## Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System ✓

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Fog Lights ✓

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Rear Blower Switch ✓

Rear Left AC Vent ✓

Power/ Manual Windows ✓

## Interiors & Luggage

Dashboard And Instrument Panel ✓

Central Console ⓘ
Box: Minor Color Low Brightness

Cup Holder ✓

Steering Wheel ✓

Sunvisor ✓

Seat Upholstery ⓘ
Rear Right Seat: Cigarette Burn

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet ✓

Headliner ✓

Rear View Mirror ✓

Toolkit ✓

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <75% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE