

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 KAIYI X3 PRO

LUXURY | 80,177 KM

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	80177	Specs	Yes
Engine	1.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Grey
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LUYJB2G27RA004111		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓		
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm

Rear left door
Panel: Scuffing

Rear right door
Panel: Low Visual Dent < 30mm, Scuffing > 50mm

Fenders Condition

Left Fender
Condition: Light Scuffing

Right Fender
Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Light Scuffing

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement, Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm

Rear Windshield
Light Scuffing < 50mm

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Grill Condition Scuffing > 50mm	!	Monogram	✓

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓	Turbocharger/ Supercharger	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure Warning Light

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Left: Scuff Marks > 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights

Right DRL: Low Brightness

Air Conditioning

AC Cooling

AC System Leaks

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted

Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing

Steering Wheel

Sunvisor

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Front Left Floor Mat: Smudge/Burn/Crack

Headliner

Rear View Mirror

Toolkit

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE