

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2026 CHERY TIGGO 7

COMFORT | 38,601 KM

VIN: LVVDB21BXTDD04028

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	38601	Specs	Yes
Engine	1.5L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Leather Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LVVDB21BXTDD04028		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Performance			
Hill Descent Control	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door	✓		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Low Visual Dent, Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Fully Repainted, Paint Faded	!

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top
Fair Use Wear/Crack<5mm

Rear View Mirror Condition

Left Hand Side Mirror
Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim
Left Rear Alloy/ Rim
Right Front Alloy/ Rim
Right Rear Alloy/ Rim

Grill Condition
Light Scuffing < 50mm
Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body
Engine Performance
Engine Oil (Condition & Level)
Exhaust System
Turbocharger/ Supercharger
Radiator Condition
Radiator Coolant

Transmission Operation

Gear Shifting
Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake
Brake Master Cylinder
Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel ✓

Controls ✓ | Cruise Control ✓

Infotainment Display ✓ | Music System ✓

Camera ✓

Lights

Headlight ✓ | Interior Lights ✓

Tail Light Cluster ✓ | Daylight Running Lights ✓

Air Conditioning

AC Cooling ✓ | AC System Leaks ✓

Rear Blower Switch ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted ⓘ | Central Console ✓

Cup Holder ✓ | Steering Wheel

Steering Wheel Fair Use Wear ⓘ

Sunvisor ✓ | Seat Upholstery ✓

Manual Seat Movement ✓ | Seat Belts ✓

Head Rest ✓ | Door Controls And Trim ✓

Carpet

Front Left Floor Mat: Smudge/Burn/Crack ⓘ | Headliner ✓

Rear View Mirror ✓ | Toolkit ✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE