


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2025 GEELY STARRAY**

**GL | 50,334 KM**

VIN: LB3FX1S63SB004439

## Car highlights

### Cruise control

Cruise control to drive with ease & comfort

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 50334 | Specs | Yes |
| Engine | 2.0L | Option Type | Basic |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Other |
| Interior Trim | Leather Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | LB3FX1S63SB004439 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Power Windows Rear | ✓ | | |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |

| | | | |
|---|---|---|---|
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |
| **Exteriors** | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | | |
| **Performance** | | | |
| Hill Descent Control | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

| | | | |
|---|---|---|---|
| **Doors condition** | | | |
| Front right door<br>Panel: Paint Chip-off < 5mm | ! | Rear left door | ✓ |
| Rear right door | ✓ | | |
| **Fenders Condition** | | | |
| Left Fender | ✓ | Right Fender | ✓ |
| **Quarter Panels Condition** | | | |
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |
| **Rear Bumper Condition** | | | |
| Rear Bumper | ✓ | | |
| **Hood Condition** | | | |
| Hood | ✓ | | |
| **Roof Condition** | | | |
| Roof | ✓ | | |
| **Running Board Condition** | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| **Windshield Condition** | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| **Structural Assessment** | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |
| **Cowl Top** | | | |
| Cowl Top | ✓ | | |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Right Side Mirror | ✓ |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |

Panel Condition

| | |
|---|---|
| Rear Trunk Panel | ✓ |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid | ✓ | | |

Suspension

| | |
|---|---|
| Shock Absorbers | ✓ |

## Electricals, Controls & Lights

Keys

| | |
|---|---|
| Master Key | ✓ |

Dashboard

| | |
|---|---|
| Instrument Panel | ✓ |

| | | | |
|---|---|---|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Music System | ✓ |
| Camera | ✓ | | |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Blower Switch | ✓ | | |
| Power/ Manual Windows | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <65% | LHS Rear Tyre | <55% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <85% |
| Spare Tyre | <65% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE