


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2024 NISSAN SUNNY**

**SV | 38,261 KM**

VIN: MDHBN7AD3RG516703

## Car highlights

### Fuel Efficient

Fuel efficient with 18.0 km/L

### Great Parking Assistance

Reverse Camera, Parking Sensors Rear

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 38261 | Specs | Yes |
| Engine | 1.5L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel Efficiency | 18.0 km/L mileage |
| Wheel Type | Steel Wheels | Exterior Color | Exterior Color White |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | MDHBN7AD3RG516703 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security | | | |
|---|---|---|---|
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |

| Comfort & Convenience | | | |
|---|---|---|---|
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |

| Entertainment | |
| --- | --- |
| Bluetooth Player | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

Front right door
Panel: Scuffing > 50mm, Low Visibility Dent < 30mm

Rear left door
Panel: Colour faded

Rear right door
Panel: Paint Defect, Colour Mismatch/ Low Brightness

### Fenders Condition

Left Fender

Right Fender
Right Fender: Dent

### Quarter Panels Condition

Left Quarter Panel
Condition: Colour faded

Right Quarter Panel

### Rear Bumper Condition

Rear Bumper
Rear Bumper: Fully Repainted, Crack/ Misaligned

### Hood Condition

Hood

### Roof Condition

Roof

### Running Board Condition

Left Running Board

Right Running Board

### Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor<br>Condition: Trunk floor dent | ! | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

| | | | |
|---|---|---|---|
| Cowl Top | ✓ | | |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Right Side Mirror | ✓ |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition<br>Fully Repainted | ! | Monogram | ✓ |

Panel Condition

| | | | |
|---|---|---|---|
| Rear Trunk Panel<br>Dent | ! | | |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |

Suspension

| | | | |
|---|---|---|---|
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Infotainment Display

Infotainment Display: Damaged Display

Music System

Camera

Lights

Headlight

Left: Scuff Marks > 50mm

Interior Lights

Tail Light Cluster

Air Conditioning

AC Cooling

Rear Left AC Vent

Parking Sensors

Power/ Manual Windows

## Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Cup Holder

Steering Wheel

Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Trunk Floor Carpet: Floor carpet damage

Headliner

Rear View Mirror

Toolkit

## Tyres

Tyres Condition

Left Hand Side Front Tyre

Left Hand Side Rear Tyre

| | | | |
|---|---|---|---|
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <75% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE