

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 HAVAL H6

MEDIUM | 61,687 KM

VIN: LGWEF6A53RH921636

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	61687	Specs	Yes
Engine	2.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Grey
Interior Trim	Fabric Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LGWEF6A53RH921636		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender Condition: Fender liner missing/ damaged/ misaligned, Low Visual Dent	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Chip	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Colour Mismatch/ Low Brightness, Dent < 50mm	!		

Hood Condition

Hood	✓		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield Wiper blade damaged	!

Structural Assessment

Chassis Condition	✓	Apron	✓

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition Scuffing > 50mm	!	Monogram	✓

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Coolant	✓

Transmission Operation

Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror Mirror Assembly Loose	!	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<45%	LHS Rear Tyre	<45%
RHS Front Tyre	<45%	RHS Rear Tyre	<45%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE