

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 EXEED TXL

COMFORT | 79,243 KM

VIN: LVTDB21B8RD012506

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	79243	Specs	Yes
Engine	1.6L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Leather Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LVTDB21B8RD012506		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	Side Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓

Comfort & Convenience	
Climate Control AC ✓	Cruise Control ✓
Power Window front - Drivers Side ✓	Power Window front - Passenger Side ✓
Power Tailgate/ Power Trunk ✓	Power Windows Rear ✓
Exteriors	
Fog Light Front ✓	Roof Rails ✓
Running Lights ✓	Rear Bumper Spoiler ✓
Entertainment	
Bluetooth Player ✓	Apple Play ✓
Android Auto Play ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm	!	Rear left door	✓
Rear right door	✓		

Fenders Condition

Left Fender Condition: Dent	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Light Scuffing < 50mm

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Turbocharger/ Supercharger

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows	✓	Seat Heaters	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE