

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 HAVAL H6

MEDIUM | 72,363 KM

VIN: LGWEF6A57RH924202

Car highlights

Boosted Engine

This car has a Boosted Engine

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	72363	Specs	Yes
Engine	2.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LGWEF6A57RH924202		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm

Rear left door

Rear right door
Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender
Condition: Light Scuffing

Right Fender
Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Rear Bumper Condition

Rear Bumper
Rear Bumper: Scuffing > 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition

Apron

Boot Floor

Firewall Condition

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Fully Repainted

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Turbocharger/ Supercharger

Radiator Condition

Dry coolant mark - hoses

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel
Malfunction Indication Lights: Engine Temperature Warning Light

Controls ✓
Cruise Control ✓
Infotainment Display ✓
Music System ✓
Camera ✓

Lights

Headlight ✓
Interior Lights ✓
Tail Light Cluster ✓
Daylight Running Lights
Right DRL: Low Brightness
Fog Lights ✓

Air Conditioning

AC Cooling ✓
AC System Leaks ✓
Rear Blower Switch ✓
Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted
Central Console
Box: Lock Damage
Cup Holder ✓
Steering Wheel
Steering Wheel Fair Use Wear
Sunvisor ✓
Seat Upholstery ✓
Manual Seat Movement ✓
Seat Belts ✓
Head Rest ✓
Door Controls And Trim ✓
Carpet
Front Left Floor Mat: Smudge/Burn/Crack
Headliner ✓
Rear View Mirror
Damaged Mirror Casing
Toolkit ✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE