

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2025 JETOUR X 70 PLUS

COMFORT | 39,435 KM

VIN: LVTDB21B8SD606129

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	39435	Specs	Yes
Engine	1.6L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	4 Airbags
Seating Capacity	7 Seats	Number of keys	2 Keys
VIN number	LVTDB21B8SD606129		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Lane Departure Warning System	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Front Camera	✓
Side Camera	✓	Airbag Sides	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓		
Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Performance			
Hill Descent Control	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm

Rear left door

Rear right door
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender
Condition: Light Scuffing

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Scuffing > 80mm, Paint Faded

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake Cover Fair Use Wear	!	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel

Central Console
Gear Shift Knob: Knob Fair Use Wear

Cup Holder

Steering Wheel
Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet
Front Left Floor Mat: Smudge/Burn/Crack

Headliner

Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE