

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 DODGE CHALLENGER

R/T | 86,666 KM

VIN: 2C3CDZBTXPH597438

Car highlights

Power packed

Engine size of 5.7 Litres & 8.0 cylinders

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

Kilometers	86666	Specs	Yes
Engine	5.7L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Rear Wheel Drive
Body Type	COUPE	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Blue
Interior Trim	Partial Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	2C3CDZBTXPH597438		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Ventilated Seat	✓
Exteriors			
Fog Light Front	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Performance			
Paddle Shift	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Paint Defect, Scuffing > 50mm	!

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror
Body: Scuffing

Right Side Mirror
Body: Scuffing

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim
Rim: Alloy Edge Scuffing

Right Front Alloy/ Rim
Rim: Alloy Edge Scuffing

Right Rear Alloy/ Rim
Rim: Alloy Edge/Scuffing

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Coolant

Transmission Operation

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Electricals, Controls & Lights

Keys

Master Key
Central Locking Not Working

Dashboard

Instrument Panel

Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera Reverse Camera: Lens Damaged/ Blurred	!		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows Front Left: Power Window Noise/Vibration	!	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Life remaining

LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE