

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 HYUNDAI TUCSON

GLS | 100,443 KM

VIN: TMAJ381B4JJ610283

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	100443	Specs	Yes
Engine	2.4L	Option Type	Fully Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel Efficiency	12.0 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	TMAJ381B4JJ610283		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓		
Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Performance			
Hill Descent Control	✓	Differential Locks	✓
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Door inner sealant repaired / corroded / damaged

Rear left door

Rear right door
Panel: Paint Chip-off > 5mm, Light Scuffing < 50mm, Low Visual Dent < 30mm

Fenders Condition

Left Fender
Condition: Low Visual Dent

Right Fender
Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent, Light Scuffing

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement, Air Bubbles	⚠	Rear Windshield Wiper blade damaged	⚠

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror Body: Scuffing	⚠	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers

Electricals, Controls & Lights

Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure Warning Light

Cruise Control

Infotainment Display

Music System

Condition: Not Working

Camera

Reverse Camera: Not Working

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Fog Lights

Air Conditioning

AC Cooling

AC Temperature: Missing control knobs/ Broken

AC System Leaks

Rear Blower Switch

Crack

Parking Sensors

Power/ Manual Windows

Seat Heaters

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear

Central Console

Gear Shift Knob: Knob Fair Use Wear

Cup Holder

Steering Wheel

Steering Wheel Fair Use Wear

Sunvisor

Left: Sunvisor LHS Crack/ Fair Use Wear, Sunvisor RHS Major Crack/Damage

Seat Upholstery

Driver Seat: Smudge/ Cracks

Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror Damaged Mirror Casing	!	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE