

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 CHEVROLET GROOVE

LT | 22,592 KM

VIN: LZWADAGA6PF007925

Car highlights

Low Mileage

This car has been driven less than 15,000 km a year

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	22592	Specs	Yes
Engine	1.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	15.4 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LZWADAGA6PF007925		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm, Scuffing > 50mm

Rear left door

Rear right door
Panel: Dent > 30mm, Scuffing > 50mm

Fenders Condition

Left Fender

Right Fender
Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Rear Bumper Condition

Rear Bumper

Hood Condition

Hood

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition

Apron

Boot Floor

Firewall Condition

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror
Body: Paint Faded

Right Side Mirror
Body: Paint Defects

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim
Rim: Alloy Face/Light Scuffing

Grill Condition
Light Scuffing < 50mm

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Turbocharger/ Supercharger

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Front Map Reading Light: Front Map Reading Light Switch Not Working

Tail Light Cluster

Daylight Running Lights

Air Conditioning

AC Cooling

AC System Leaks

Power/ Manual Windows

Front Left: Power Window Not Working

Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Steering Wheel

Sunvisor

Seat Upholstery

Passenger Seat: Smudge/Cracks/Fair Use Wear > 10mm

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Headliner

Rear View Mirror

Damaged Mirror Casing

Toolkit

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE