

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 CHEVROLET GROOVE

LT | 38,014 KM

VIN: LZWADAGA0PF007340

Car highlights

Low Mileage

This car has been driven less than 15,000 km a year

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	38014	Specs	Yes
Engine	1.5L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	15.4 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	LZWADAGA0PF007340		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Driver Front	✓

Airbag Passenger Front	✓	ABS	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm

Rear left door

Rear right door
Panel: Dent > 30mm, Scuffing > 50mm

Fenders Condition

Left Fender
Condition: Paint Chip-off

Right Fender
Right Fender: Dent

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent, Light Scuffing

Rear Bumper Condition

Rear Bumper
Rear Bumper: Fully Repainted, Dent < 50mm, Light Scuffing < 80mm, Crack/ Misaligned

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm

Roof Condition

Roof
Roof Moulding Condition: Colour fade

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Air Bubbles, Front Wiper blades need replacement

Rear Windshield
Wiper blade damaged

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror Body: Paint Faded	!	Right Side Mirror Body: Paint Defects	!

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Grill Condition Fully Repainted	!	Monogram	✓

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake Cover Fair Use Wear	!	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System ✓

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Daylight Running Lights ✓

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Power/ Manual Windows

Front Left: Power Window Noise/Vibration !

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted !

Central Console

Gear Shift Knob: Knob Fair Use Wear !

Steering Wheel

Steering Wheel Fair Use Wear !

Sunvisor ✓

Seat Upholstery ✓

Manual Seat Movement

Rear Seat: Adjuster Lever Stuck !

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet

Front Left Floor Mat: Smudge/Burn/Crack !

Headliner ✓

Rear View Mirror

Crack In Mirror !

Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<45%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE