

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 PEUGEOT 2008

ACTIVE | 81,274 KM

VIN: VR3UYNFJ9PJ515301

Car highlights

Fuel Efficient

Fuel efficient with 17.0 km/L

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	81274	Specs	Yes
Engine	1.6L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	17.0 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Grey
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	VR3UYNFJ9PJ515301		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm, Scuffing > 50mm	!	Rear left door	✓
Rear right door Panel: Scuffing > 50mm, Low Visual Dent < 30mm	!		

Fenders Condition

Left Fender Condition: Paint Chip-off	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Low Visual Dent	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm	!		

Hood Condition

Hood	✓		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Fully Repainted

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Front Brake Discs Thickness < Manufacturer Standard

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure Warning Light

Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre	✓

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE