

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 KIA SELTOS

LX | 53,761 KM

VIN: LJD5AA1D5R0104148

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	53761	Specs	Yes
Engine	1.6L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	LJD5AA1D5R0104148		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Safety & Security			
Reverse Camera	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door	✓	Rear left door	✓
Rear right door Panel: Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm	!

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield Wiper blade damaged	!

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Broken/ Fair Use Wear

Monogram

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts Driver Seat: Buckle Limited Movement	!	Head Rest	✓
Door Controls And Trim	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE