


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2025 JETOUR T2**

**LUXURY | 19,194 KM**

VIN: 97148432169714843

## Car highlights

### Great condition

Car has low imperfections

### Panoramic Roof

This car has a panoramic roof

### Music System

Enjoy your drive with music system

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 19194 | Specs | Yes |
| Engine | 2.0L | Option Type | Fully Loaded |
| Transmission | Automatic | Drive | Four Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color White |
| Interior Trim | Partial Leather Trim | Number of Airbags | 6 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | 97148432169714843 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Panoramic Sunroof | ✓ | Memory Seats | ✓ |
| **Safety & Security** | | | |
| Reverse Camera | ✓ | | |
| **Entertainment** | | | |
| Infotainment System | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door | ✓ | Rear left door | ✓ |
| Rear right door | ✓ | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Boot Floor | ✓ |
| Head Light Support Condition | ✓ | | |

### Cowl Top

| | | | |
|---|---|---|---|
| Cowl Top | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

## Engine & Transmission

| | | | |
|---|---|---|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

| | | | |
|---|---|---|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

| | | | |
|---|---|---|---|
| Keys | | | |
| Master Key | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |

| | | | |
|---|---|---|---|
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | | |
| Power/ Manual Windows | ✓ | Memory Seats | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Headliner | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE