


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2023 MAZDA 6**

**S | 77,474 KM**

VIN: JM7GL4S35P1486075

## Car highlights

### Great condition

Car has low imperfections

### Cruise control

Cruise control to drive with ease & comfort

### Music System

Enjoy your drive with music system

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 77474 | Specs | Yes |
| Engine | 2.5L | Option Type | Basic |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel Efficiency | 14.0 km/L mileage |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Grey |
| Interior Trim | Fabric Trim | Number of Airbags | 6 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | JM7GL4S35P1486075 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Comfort & Convenience | | | |
|---|---|---|---|
| Cruise Control | ✓ | Power Window front - Drivers Side | ✓ |
| Power Window front - Passenger Side | ✓ | Power Windows Rear | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door | ✓ | Rear left door | ✓ |
| Rear right door | ✓ | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper<br>Rear Bumper: Fully Repainted | ! |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Boot Floor | ✓ |
| Head Light Support Condition | ✓ | | |

### Cowl Top

Cowl Top

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Fully Repainted

Panel Condition

Rear Trunk Panel

## Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Turbocharger/ Supercharger

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

## Steering, Suspension & Brakes

Steering

Steering wheel

Brake System

Parking Brake

Brake Master Cylinder

Suspension

Shock Absorbers

## Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

| | | | |
|---|---|---|---|
| Controls | ✓ | Infotainment Display | ✓ |
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | | |
| Power/ Manual Windows | ✓ | Memory Seats | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel | ✓ | Headliner | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE