

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 JETOUR DASHING

LUXURY | 55,790 KM

VIN: HJRPBGGB9RB156219

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

Kilometers	55790	Specs	Yes
Engine	1.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	8 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	HJRPBGGB9RB156219		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Lane Departure Warning System	✓
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Front Camera	✓	Side Camera	✓

Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Ventilated Seat	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			
Running Lights	✓	Rear Bumper Spoiler	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Dent > 30mm	!	Rear left door	✓
Rear right door Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visual Dent < 30mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	!		

Hood Condition

Hood Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm	!		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓		

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip Mark<5mm	!	Rear Windshield	✓

Structural Assessment

Chassis Condition Chassis Extension: Bumper frame repaired/Replaced	!	Apron	✓

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition Repaired/Replaced	!		

Cowl Top

Cowl Top	✓		

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key Button Faded	!		

Dashboard

Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓

Lights

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE