

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 NISSAN PATROL

XE | 91,755 KM

VIN: JN8BY2NY0K9195399

Car highlights

Power packed

Engine size of 4.0 Litres & 6.0 cylinders

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	91755	Specs	Yes
Engine	4.0L	Option Type	Basic
Transmission	Automatic	Drive	Four Wheel Drive
Body Type	SUV	Fuel Efficiency	6.75 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	2 Airbags
Seating Capacity	8 Seats	Number of keys	2 Keys
VIN number	JN8BY2NY0K9195399		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		

Exteriors			
Fog Light Front	✓	Roof Rails	✓

Safety & Security	
Parking Sensors Front ✓	Parking Sensors Rear ✓
Reverse Camera ✓	Airbag Driver Front ✓
Airbag Passenger Front ✓	ABS ✓
Performance	
Hill Descent Control ✓	Differential Locks ✓
Entertainment	
Bluetooth Player ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Low Visual Dent, Light Scuffing	!

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓

Head Light Support Condition ✓

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition
Scuffing > 50mm ! | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

4*4 Condition (If Applicable) ✓

Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System
Steering Mounted Audio Controls: Not Working Properly !

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Fog Lights ✓

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Rear Blower Switch ✓

Rear Left AC Vent ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted !

Central Console
Gear Shift Knob: Knob Fair Use Wear !

Cup Holder ✓

Steering Wheel
Steering Wheel Fair Use Wear !

Sunvisor ✓

Seat Upholstery
Driver Seat: Minor Smudge/ Cracks !

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet !

Headliner ✓

Front Left Floor Mat: Smudge/Burn/Crack

Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE