

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 MERCEDES BENZ GLE 450

4MATIC | 42,052 KM

VIN: W1NFB5KE8RB034580

Car highlights

Great condition

Car has low imperfections

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	42052	Specs	Yes
Engine	3.0L	Option Type	Fully Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	8 Airbags
Seating Capacity	7 Seats	Number of keys	2 Keys
VIN number	W1NFB5KE8RB034580		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Lane Departure Warning System	✓
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Auto Park Assist	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Front Camera	✓

Side Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Tailgate/ Power Trunk	✓
Power Windows Rear	✓		
Performance			
Paddle Shift	✓		
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door	✓	Rear left door	✓
Rear right door	✓		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key	✓		

Dashboard

Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE