

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2025 MITSUBISHI OUTLANDER

H/L SYNTHETIC LEATHER SUNROOF | 32,582 KM

VIN: JE4M4W18XSZ701761

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Android Auto

Enjoy your drive with Android Auto

Amazing Comfort

Power driver seat

Basic Details

Kilometers	32582	Specs	Yes
Engine	2.5L	Option Type	Fully Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Grey
Interior Trim	Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	7 Seats	Number of keys	1 Keys
VIN number	JE4M4W18XSZ701761		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Safety & Security			
Lane Departure Warning System	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Performance			
Paddle Shift	✓		
Entertainment			
Bluetooth Player	✓	Android Auto Play	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Scuffing > 50mm, Dent > 30mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel Condition: Dent, Scuffing	!	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Crack/ Misaligned, Dent > 50mm, Scuffing > 80mm	!

Hood Condition

Hood	✓

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass Noise/Vibration	!

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor Condition: Light Rusting	!	Firewall Condition	✓
Head Light Support Condition Crack/ Fair use Wear	!		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Left Rear Alloy/ Rim Rim: Alloy Face Scuffing	!
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Performance	✓	Engine Oil (Condition & Level)	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key	✓

Dashboard

Instrument Panel	✓
Controls	✓
Cruise Control	✓
Infotainment Display	✓
Music System	✓
Camera	✓

Lights

Headlight	✓
Interior Lights	✓
Tail Light Cluster	✓
Daylight Running Lights	✓
Fog Lights	✓

Air Conditioning

AC Cooling	✓
AC System Leaks	✓
Rear Blower Switch	✓
Rear Left AC Vent	✓
Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓
Central Console	✓
Cup Holder	✓
Steering Wheel	✓
Sunvisor	✓
Seat Upholstery Driver Seat: Smudge/ Cracks	!
Manual Seat Movement	✓
Seat Belts	✓
Head Rest	✓
Door Controls And Trim	✓
Carpet	✓
Headliner	✓
Rear View Mirror	✓
Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE