

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 SUZUKI CIAZ

GL | 72,636 KM

VIN: MA3VC7A11RA490983

Car highlights

Fuel Efficient

Fuel efficient with 21.0 km/L

Great Parking Assistance

Reverse Camera

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	72636	Specs	Yes
Engine	1.5L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	21.0 km/L mileage
Wheel Type	Steel Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MA3VC7A11RA490983		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Reverse Camera	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Comfort & Convenience			
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		

Entertainment	
Bluetooth Player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing, Paint Chip-off	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Low Visual Dent	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Dent < 50mm	!		

Hood Condition

Hood Bonnet: Light Scuffing < 50mm, Dent > 30mm	!		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board Condition: Dent > 50mm, Light Scuffing < 80mm	!

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓

Boot Floor Condition: Rear End Panel Repaired	!	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Grill Condition Light Scuffing < 50mm	!	Monogram	✓

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Infotainment Display

Music System

Camera
Reverse Camera: Lens Damaged/ Blurred

Lights

Headlight

Interior Lights

Tail Light Cluster

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted

Central Console
Gear Shift Knob: Knob Fair Use Wear

Cup Holder

Steering Wheel
Color Faded

Sunvisor
Left: Sunvisor RHS Minor Crack/Damage

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet
Front Left Floor Mat: Smudge/Burn/Crack

Headliner

Rear View Mirror

Toolkit

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<45%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE