

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2020 INFINITI Q50

LUXE | 100,147 KM

VIN: JN1EV7APXLM430162

Car highlights

Sunroof

This car has a sunroof

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	100147	Specs	Yes
Engine	3.0L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Rear Wheel Drive
Body Type	SEDAN	Fuel Efficiency	8.0 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Blue
Interior Trim	Partial Leather Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	JN1EV7APXLM430162		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓	Running Lights	✓
Comfort & Convenience			
Cruise Control	✓	Memory Seats	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		

Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm	!	Rear left door	✓
Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	!		

Hood Condition

Hood	✓		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓		

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top Fair Use Wear/Crack<5mm	!

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System ✓

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Daylight Running Lights ✓

Fog Lights ✓

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Rear Blower Switch ✓

Power/ Manual Windows ✓

Seat Heaters ✓

Memory Seats ✓

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted !

Central Console ✓

Cup Holder ✓

Steering Wheel

Steering Wheel Fair Use Wear !

Sunvisor ✓

Seat Upholstery ✓

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE