


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2021 TOYOTA FORTUNER**

**EXR | 95,820 KM**

VIN: MHFDX8FS7M0113619

## Car highlights

### Four wheel drive

This car has a Four wheel drive

### Cruise control

Cruise control to drive with ease & comfort

### Android Auto

Enjoy your drive with Android Auto

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 95820 | Specs | Yes |
| Engine | 2.7L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Four Wheel Drive |
| Body Type | SUV | Fuel Efficiency | 9.75 km/L mileage |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Grey |
| Interior Trim | Fabric Trim | Number of Airbags | 3 Airbags |
| Seating Capacity | 7 Seats | Number of keys | 2 Keys |
| VIN number | MHFDX8FS7M0113619 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Cruise Control | ✓ | Power Window front - Drivers Side | ✓ |
| Power Window front - Passenger Side | ✓ | Power Windows Rear | ✓ |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Knees | ✓ | Airbag Driver Front | ✓ |

| | | | |
|---|---|---|---|
| Airbag Passenger Front | ✓ | ABS | ✓ |
| **Exteriors** | | | |
| Roof Rails | ✓ | Rear Bumper Spoiler | ✓ |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Android Auto Play | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Low Visibility Dent < 30mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Low Visual Dent < 30mm | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender<br>Condition: Low Visual Dent, Light Scuffing | ! | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel<br>Condition: Quarter glass beading damaged | ! |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper<br>Rear Bumper: Dent < 50mm | ! |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition

Light Scuffing < 50mm ⓘ | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

4*4 Condition (If Applicable) ✓

## Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓ | Cruise Control ✓

Infotainment Display ✓ | Music System ✓

Camera ✓

Lights

Headlight ✓ | Interior Lights ✓

Tail Light Cluster ✓ | Daylight Running Lights ✓

Air Conditioning

AC Cooling ✓ | AC System Leaks ✓

Rear Blower Switch ✓ | Rear Left AC Vent ✓

Power/ Manual Windows ✓

## Interiors & Luggage

Dashboard And Instrument Panel ✓ | Central Console ✓

Cup Holder ✓ | Steering Wheel ✓

Sunvisor ✓ | Seat Upholstery ✓

Manual Seat Movement ✓ | Seat Belts ✓

Head Rest ✓ | Door Controls And Trim ✓

Carpet ✓ | Headliner ✓

Rear View Mirror ✓ | Toolkit ✓

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE