


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2020 MITSUBISHI PAJERO**

**GLS SIGNATURE EDITION | 64,669 KM**

VIN: JE4NR62R0LJ716380

## Car highlights

### Four wheel drive

This car has a Four wheel drive

### Cruise control

Cruise control to drive with ease & comfort

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 64669 | Specs | Yes |
| Engine | 3.8L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Four Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Black white |
| Interior Trim | Leather Trim | Number of Airbags | 6 Airbags |
| Seating Capacity | 7 Seats | Number of keys | 2 Keys |
| VIN number | JE4NR62R0LJ716380 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Comfort & Convenience | | | |
|---|---|---|---|
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Power Windows Rear | ✓ | | |

| Exteriors | | | |
|---|---|---|---|
| Fog Light Front | ✓ | Roof Rails | ✓ |

| | | | |
|---|---|---|---|
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Blind Spot Monitor | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |
| **Entertainment** | | | |
| Rear Seat Entertainment | ✓ | Bluetooth Player | ✓ |
| **Performance** | | | |
| Hill Descent Control | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

| | | | |
|---|---|---|---|
| **Doors condition** | | | |
| Front right door<br>Panel: Light Scuffing < 50mm | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Light Scuffing < 50mm | ! | | |
| **Fenders Condition** | | | |
| Left Fender | ✓ | Right Fender | ✓ |
| **Quarter Panels Condition** | | | |
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |
| **Rear Bumper Condition** | | | |
| Rear Bumper | ✓ | | |
| **Hood Condition** | | | |
| Hood<br>Bonnet: Light Scuffing < 50mm | ! | | |
| **Roof Condition** | | | |
| Roof | ✓ | | |
| **Running Board Condition** | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| **Sunroof Glass Condition (If Equipped)** | | | |
| Sun Roof Glass | ✓ | | |
| **Windshield Condition** | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| **Structural Assessment** | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |

| | | | |
|---|---|---|---|
| Head Light Support Condition | ✓ | | |
| **Cowl Top** | | | |
| Cowl Top | ✓ | | |
| **Rear View Mirror Condition** | | | |
| Left Hand Side Mirror | ✓ | Right Side Mirror | ✓ |
| **Alloy Wheel/ Rim** | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram | ✓ | | |
| **Panel Condition** | | | |
| Rear Trunk Panel | ✓ | | |

## Engine & Transmission

| | | | |
|---|---|---|---|
| **Engine** | | | |
| Engine Body<br>Underbody: Major Rusted | ! | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| **Transmission Operation** | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | | |

## Steering, Suspension & Brakes

| | | | |
|---|---|---|---|
| **Steering** | | | |
| Steering wheel | ✓ | | |
| **Brake System** | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid | ✓ | | |
| **Suspension** | | | |
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

### Keys

| | |
|---|---|
| Master Key | ✓ |

### Dashboard

| | |
|---|---|
| Instrument Panel | ✓ |
| Controls | ✓ |
| Cruise Control | ✓ |
| Infotainment Display | ✓ |
| Music System | ✓ |
| Camera | ✓ |

### Lights

| | |
|---|---|
| Headlight | ✓ |
| Interior Lights | ✓ |
| Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |
| Fog Lights | ✓ |

### Air Conditioning

| | |
|---|---|
| AC Cooling | ✓ |
| AC System Leaks | ✓ |
| Rear Blower Switch | ✓ |
| Rear Left AC Vent<br>RHS Crack/Fair Use Wear | ! |
| Rear Entertainment | ✓ |
| Power/ Manual Windows | ✓ |

## Interiors & Luggage

### Dashboard And Instrument Panel

| | |
|---|---|
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! |
| Central Console | ✓ |
| Cup Holder | ✓ |
| Steering Wheel<br>Steering Wheel Fair Use Wear | ! |
| Sunvisor | ✓ |
| Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ |
| Seat Belts | ✓ |
| Head Rest | ✓ |
| Door Controls And Trim | ✓ |

| | | | |
|---|---|---|---|
| Carpet<br>Front Left Floor Mat: Smudge/Burn/Crack | ! | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <85% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <75% |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE