


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**12 Months Warranty**

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.




**2024 VOLVO XC60**

**B5 ULTIMATE BLACK EDITION | 15,426 KM**

VIN: YV1L5AUZ9R1928615

## Car highlights

### Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat, Memory Seats

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 15426 | Specs | Yes |
| Engine | 2.0L | Option Type | Fully Loaded |
| Transmission | Automatic | Drive | All Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Black |
| Interior Trim | Leather Trim | Number of Airbags | 8 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 2 Keys |
| VIN number | YV1L5AUZ9R1928615 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Comfort & Convenience | | | |
|---|---|---|---|
| Heads up Display | ✓ | Climate Control AC | ✓ |
| Cruise Control | ✓ | Memory Seats | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Power Tailgate/ Power Trunk | ✓ | Cool Box | ✓ |
| Power Windows Rear | ✓ | | |

| | | | |
|---|---|---|---|
| **Safety & Security** | | | |
| Adaptive cruise control | ✓ | 360 degree Camera | ✓ |
| Lane Departure Warning System | ✓ | Navigation | ✓ |
| Parking Sensors Front | ✓ | Parking Sensors Rear | ✓ |
| Auto Park Assist | ✓ | Reverse Camera | ✓ |
| Blind Spot Monitor | ✓ | Collision Warning System | ✓ |
| Front Camera | ✓ | Side Camera | ✓ |
| Airbag Sides | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |
| **Exteriors** | | | |
| Fog Light Front | ✓ | Running Lights | ✓ |
| **Performance** | | | |
| Hill Descent Control | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed** ✓

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door | ✓ | Rear left door | ✓ |
| Rear right door | ✓ | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

### Hood Condition

| | |
|---|---|
| Hood | ✓ |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

| | | | |
|---|---|---|---|
| Cowl Top | ✓ | | |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Right Side Mirror | ✓ |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim<br>Rim: Alloy Edge Scuffing | ! |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram | ✓ | | |

Panel Condition

| | | | |
|---|---|---|---|
| Rear Trunk Panel | ✓ | | |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid | ✓ | | |

Suspension

| | | | |
|---|---|---|---|
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

Keys

| | | | |
|---|---|---|---|
| Master Key | ✓ | | |

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Music System | ✓ |
| Camera | ✓ | | |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Blower Switch | ✓ | Rear Left AC Vent | ✓ |
| Rear Entertainment | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <55% | LHS Rear Tyre | <55% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <55% |
| Spare Tyre | <55% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE