

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 HYUNDAI KONA

COMFORT | 49,261 KM

VIN: KMHK281B1MU727353

Car highlights

Low Mileage

This car has been driven less than 15,000 km a year

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	49261	Specs	Yes
Engine	2.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	HATCHBACK	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Red
Interior Trim	Fabric Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	KMHK281B1MU727353		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Roof Rails	✓

Running Lights	✓	Rear Bumper Spoiler	✓
Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Low Visibility Dent < 30mm, Scuffing > 50mm, Paint Chip-off < 5mm

Rear left door

Rear right door
Panel: Low Visual Dent < 30mm, Scuffing > 50mm, Paint Chip-off < 5mm, Dent > 30mm

Fenders Condition

Left Fender
Condition: Fender liner missing/ damaged/ misaligned

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Low Visual Dent, Scuffing/ Scratch

Rear Bumper Condition

Rear Bumper
Rear Bumper: Dent < 50mm, Scuffing > 80mm

Hood Condition

Hood
Bonnet: Paint Damage/ Low Brightness

Roof Condition

Roof

Running Board Condition

Left Running Board

Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass
Noise/Vibration

Windshield Condition

Front Windshield	✓	Rear Windshield Wiper blade damaged	!

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing	!
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel Scratch	!		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key

Remote/Functions Not Responding !

Dashboard

Instrument Panel ✓

Controls ✓ | Cruise Control ✓

Infotainment Display ✓ | Music System ✓

Camera ✓

Lights

Headlight ✓ | Interior Lights ✓

Tail Light Cluster ✓ | Daylight Running Lights ✓

Fog Lights ✓

Air Conditioning

AC Cooling

AC Temperature: Ac vents broken/ damaged ! | AC System Leaks ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel ✓ | Central Console ✓

Cup Holder ✓ | Steering Wheel ✓

Sunvisor ✓ | Seat Upholstery ✓

Manual Seat Movement ✓ | Seat Belts ✓

Head Rest ✓ | Door Controls And Trim ✓

Carpet ✓ | Headliner !

Front Left: Smudge/Disfiguration

Rear View Mirror

Mirror Assembly Loose

Toolkit

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE