


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2020 NISSAN PATROL**

**SE TITANIUM | 73,961 KM**

VIN: JN8BY2NY2L9314264

## Car highlights

### Power packed

Engine size of 4.0 Litres & 6.0 cylinders

### Cruise control

Cruise control to drive with ease & comfort

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 73961 | Specs | Yes |
| Engine | 4.0L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Four Wheel Drive |
| Body Type | SUV | Fuel Efficiency | 6.5 km/L mileage |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Black |
| Interior Trim | Leather Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 8 Seats | Number of keys | 2 Keys |
| VIN number | JN8BY2NY2L9314264 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security | | | |
|---|---|---|---|
| 360 degree Camera | ✓ | Parking Sensors Front | ✓ |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Front Camera | ✓ | Side Camera | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |
| Cool Box | ✓ | Power Windows Rear | ✓ |
| **Exteriors** | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| Trailer Hook / Coupling | ✓ | | |
| **Performance** | | | |
| Hill Descent Control | ✓ | Differential Locks | ✓ |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door | ✓ | Rear left door | ✓ |
| Rear right door<br>Panel: Light Scuffing < 50mm | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender<br>Condition: Light Scuffing | ! | Right Fender | ✓ |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel<br>Condition: Low Visual Dent, Light Scuffing | ! |

### Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | ✓ |

### Hood Condition

| | |
|---|---|
| Hood<br>Bonnet: Light Scuffing < 50mm | ! |

### Roof Condition

| | |
|---|---|
| Roof | ✓ |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

### Cowl Top

Cowl Top
Fair Use Wear/Crack<5mm

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim
Rim: Alloy Edge Scuffing

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition ✓ | Monogram ✓

Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

4*4 Condition (If Applicable) ✓

## Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Fog Lights
Left Fog Light: Low Brightness lamps

Air Conditioning

AC Cooling

AC System Leaks

Rear Blower Switch

Rear Left AC Vent

Power/ Manual Windows

## Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Cup Holder

Steering Wheel

Sunvisor

Seat Upholstery

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet

Headliner

Rear View Mirror

Toolkit

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE