

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 GAC EMKOO

GL | 51,621 KM

VIN: LMGAT1L81R1294206

Car highlights

Boosted Engine

This car has a Boosted Engine

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat

Basic Details

Kilometers	51621	Specs	Yes
Engine	1.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Leather Trim	Number of Airbags	8 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	LMGAT1L81R1294206		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Collision Warning System	✓
Front Camera	✓	Side Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender Condition: Light Scuffing	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm	!		

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!		

Roof Condition

Roof	✓		

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓		

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Face Scuffing	!	Right Rear Alloy/ Rim	✓
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Music System ✓

Camera ✓

Lights

Headlight ✓

Interior Lights ✓

Tail Light Cluster ✓

Daylight Running Lights
Right DRL: Low Brightness !

Air Conditioning

AC Cooling ✓

AC System Leaks ✓

Rear Blower Switch ✓

Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted !

Central Console ✓

Cup Holder ✓

Steering Wheel
Steering Wheel Fair Use Wear !

Sunvisor ✓

Seat Upholstery ✓

Manual Seat Movement ✓

Seat Belts ✓

Head Rest ✓

Door Controls And Trim ✓

Carpet
Front Left Floor Mat: Smudge/Burn/Crack !

Headliner ✓

Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE