


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2024 NISSAN SUNNY**

**SV | 49,459 KM**

VIN: MDHBN7AD7RG548313

## Car highlights

### Fuel Efficient

Fuel efficient with 18.0 km/L

### Great Parking Assistance

Reverse Camera, Parking Sensors Rear

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 49459 | Specs | Yes |
| Engine | 1.5L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SEDAN | Fuel Efficiency | 18.0 km/L mileage |
| Wheel Type | Steel Wheels | Exterior Color | Exterior Color White |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 2 Keys |
| VIN number | MDHBN7AD7RG548313 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security | | | |
|---|---|---|---|
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Airbag Driver Front | ✓ | Airbag Passenger Front | ✓ |
| ABS | ✓ | | |

| Comfort & Convenience | | | |
|---|---|---|---|
| Power Window front - Drivers Side | ✓ | Power Window front - Passenger Side | ✓ |

| Entertainment | |
| --- | --- |
| Bluetooth Player | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

Front right door
Panel: Light Scuffing < 50mm, Paint Chip-off > 5mm, Paint Defect

Rear left door

Rear right door
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm

### Fenders Condition

Left Fender

Right Fender

### Quarter Panels Condition

Left Quarter Panel
Condition: Colour faded

Right Quarter Panel
Condition: Low Visual Dent, Light Scuffing

### Rear Bumper Condition

Rear Bumper
Rear Bumper: Fully Repainted, Light Scuffing < 80mm

### Hood Condition

Hood

### Roof Condition

Roof

### Running Board Condition

Left Running Board

Right Running Board

### Windshield Condition

Front Windshield

Rear Windshield

### Structural Assessment

Chassis Condition

Apron

Boot Floor

Firewall Condition

Condition: Rear End Panel Repaired

Head Light Support Condition ✓

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror ✓ | Right Side Mirror ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim ✓ | Left Rear Alloy/ Rim ✓

Right Front Alloy/ Rim ✓ | Right Rear Alloy/ Rim ✓

Grill Condition
Light Scuffing < 50mm ! | Monogram ✓

Panel Condition

Rear Trunk Panel
Water Channel Rusty !

## Engine & Transmission

Engine

Engine Body ✓ | Engine Performance ✓

Engine Oil (Condition & Level) ✓ | Exhaust System ✓

Radiator Condition ✓ | Radiator Coolant ✓

Transmission Operation

Gear Shifting ✓ | Drive Axle ✓

## Steering, Suspension & Brakes

Brake System

Parking Brake ✓ | Brake Master Cylinder ✓

Brake Fluid ✓

Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

Keys

| | | | |
|---|---|---|---|
| Master Key | ✓ | | |
| **Dashboard** | | | |
| Instrument Panel | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Music System | ✓ | Camera | ✓ |
| **Lights** | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | | |
| **Air Conditioning** | | | |
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Left AC Vent | ✓ | | |
| Parking Sensors | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery<br>Rear Right Seat: Smudge/Crack>10 mm | ! |
| Manual Seat Movement<br>Passenger Seat: Adjuster Lever Limited Movement | ! | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

| | | | |
|---|---|---|---|
| **Tyres Condition** | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |

| | | | |
|---|---|---|---|
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <65% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE