

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 MITSUBISHI ASX

GLS | 52,285 KM

VIN: JE4LPT1U0RU706375

Car highlights

Good Tyre Condition

Tyre age less than 2 years

Cruise control

Cruise control to drive with ease & comfort

Music System

Enjoy your drive with music system

Amazing Comfort

Power driver seat

Basic Details

Kilometers	52285	Specs	Yes
Engine	2.0L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Petrol
Wheel Type	Steel Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	JE4LPT1U0RU706375		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			
Navigation	✓	Reverse Camera	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Light Scuffing < 50mm	!		

Fenders Condition

Left Fender	✓	Right Fender Right Fender: Scuffing	!

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Light Scuffing	!

Rear Bumper Condition

Rear Bumper Rear Bumper: Fully Repainted, Replaced, Scuffing > 80mm	!

Hood Condition

Hood	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Boot Floor	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key	✓

Dashboard

Instrument Panel	✓

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓

Lights

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		

Air Conditioning

AC Cooling	✓

Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<73%	LHS Rear Tyre	<73%
RHS Front Tyre	<73%	RHS Rear Tyre	<73%
Spare Tyre	<73%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE