

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 BMW X6

XDRIVE40I | 99,633 KM

VIN: WBXCY6A01M9G15431

Car highlights

Panoramic Roof

This car has a panoramic roof

Cruise control

Cruise control to drive with ease & comfort

Apple play

Enjoy your drive with apple play

Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers	99633	Specs	Yes
Engine	3.0L	Option Type	Semi Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV COUPE	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	10 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	WBXCY6A01M9G15431		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Heads up Display	✓	Climate Control AC	✓
Cruise Control	✓	Memory Seats	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
Safety & Security			

360 degree Camera	✓	Lane Departure Warning System	✓
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Auto Park Assist	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Front Camera	✓
Side Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Performance			
Paddle Shift	✓	Hill Descent Control	✓
Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door	✓
Rear right door Panel: Paint Chip-off < 5mm	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel Condition: Scuffing/ Scratch	!

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood Bonnet: Paint Chip-off < 5mm	!

Roof Condition

Roof	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing	!	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing	!
Monogram	✓		

Panel Condition

Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓		

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid Front Brake Pad Thickness < 3mm	!		

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key

Smart Key Display Not Working

Dashboard

Instrument Panel

Controls

Cruise Control

Infotainment Display

Music System

Camera

Lights

Headlight

Interior Lights

Tail Light Cluster

Daylight Running Lights

Right DRL: Low Brightness

Fog Lights

Air Conditioning

AC Cooling

AC Temperature: Ac vents broken/ damaged

AC System Leaks

Rear Blower Switch

Power/ Manual Windows

Memory Seats

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted

Central Console

Cup Holder

Steering Wheel

Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks

Manual Seat Movement

Seat Belts

Head Rest

Door Controls And Trim

Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE