

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 TOYOTA COROLLA CROSS HYBRID

GLI | 65,064 KM

VIN: RKLKAAAG4R0516840

Car highlights

Great condition

Car has low imperfections

Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Music System

Enjoy your drive with music system

Amazing Comfort

Power driver seat

Basic Details

Kilometers	65064	Specs	Yes
Engine	1.8L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel	Hybrid
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Red
Interior Trim	Leather Trim	Number of Airbags	5 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	RKLKAAAG4R0516840		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Adaptive cruise control	✓	Lane Departure Warning System	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Collision Warning System	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Knees	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓

ABS	✓		
Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door	✓	Rear left door	✓
Rear right door	✓		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Boot Floor	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Radiator Condition	✓
Radiator Coolant	✓		

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key	✓

Dashboard

Instrument Panel	✓

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓

Lights

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		

Air Conditioning

AC Cooling	✓
Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE